

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1001, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1002, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1003, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1004, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1005, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1006, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1007, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1008, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1009, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1010, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1011, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1012, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1013, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1014, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1015, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1016, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1017, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1022, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1023, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1024, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1025, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1026, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1027, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1028, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1029, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1030, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1031, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1032, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1035, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1036, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1037, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1038, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1039, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1040, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1041, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1042, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1043, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1044, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1045, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1046, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1047, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1048, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1049, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1050, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1051, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1052, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1053, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1054, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1055, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences

Ref: 1979/L/1

Project Ref: 1979/P/2136

Construction Sciences Pty Ltd
ABN 74 128 806 735

3/11/2022

57-59 Mudgee Street
Kingston QLD 4114
Australia

BMD Urban
PO Box 197
WYNNUM QLD 4178

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.constructionsciences.net

Dear Sir/Madam,

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
LOT 1056, PEBBLE CREEK – STAGES 7, 8, 9 & 10**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Wayne Gorman
Lab Manager
For Brisbane South
Construction Sciences